


1 WATER LINE LAYOUT  
SCALE 1:100MTS



2 ISOMETRIC VIEW  
SCALE 1:100MTS



DepEd

PROJECT TITLE:  
RESTORATION OF GABALDON SCHOOL  
BUILDING AT BAGUIO CENTRAL SCHOOL

PROJECT LOCATION:  
YANDOC STREET, BAGUIO CITY

DRAWN BY:  
JUNELSON P. CULLADO  
TECHNICAL ASSISTANT II, EFD

CHECKED BY:  
ALDRIN JERK C. TAGAO  
MASTER PLUMBER  
ENGINEER II, EFD

REVIEWED BY:  
CARMINA AREVALO  
OIC- EXECUTIVE DIRECTOR NHCP

RECOMMENDING APPROVAL:  
OSCAR G. CASAYSAY  
EXECUTIVE DIRECTOR NCCA

APPROVED BY:  
ENGR. ANNABELLE R. PANGAN  
CHIEF  
EDUCATION FACILITIES DIVISION



APPROVED BY:  
EPIMACO V. DENSING III  
UNDERSECRETARY FOR SCHOOL  
INFRASTRUCTURE AND FACILITIES

APPROVED BY:  
SORAYA T. FACULO PhD, CESO VI  
ASSISTANT SCHOOL DIVISION SUPERINTENDENT  
OIC-OFFICE OF THE SCHOOLS DIVISION SUPERINTENDENT

SHEET CONENT:  
"AS SHOWN"

1  
P 4



 	PROJECT TITLE:	DRAWN BY:	CHECKED BY:	REVIEWED BY:		RECOMMENDING APPROVAL:	APPROVED BY:	APPROVED BY:	SHEET CONENT:	SHEET NO.:
	RESTORATION OF GABALDON SCHOOL BUILDING AT BAGUIO CENTRAL SCHOOL									
	PROJECT LOCATION:									
YANDOC STREET, BAGUIO CITY	JUNELSON P. CULLADO TECHNICAL ASSISTANT II, EFD	ALDRIN JERK C. TAGAO MASTER PLUMBER ENGINEER II, EFD	CARMINA AREVALO OIC- EXECUTIVE DIRECTOR NHCP	OSCAR G. CASAYSAY EXECUTIVE DIRECTOR NCCA	ENGR. ANNABELLE R. PANGAN CHIEF EDUCATION FACILITIES DIVISION	EPIMACO V. DENSING III UNDERSECRETARY FOR SCHOOL INFRASTRUCTURE AND FACILITIES	SORAYA T. FACULO PhD, CESO VI ASSISTANT SCHOOL DIVISION SUPERINTENDENT OIC-OFFICE OF THE SCHOOLS DIVISION SUPERINTENDENT			<div>2</div> <div>P 4</div>